# Dell Digital Switches
# Firmware Release Notes
# Version 1.26.1
# February 23, 2016

This document outlines:

1. Appliance Information
2. Enhancements
3. Fixes
4. Client/Browser

========================================================================

## 1. Appliance Information

========================================================================

The following appliances are supported with this update:

| Switch | |
|---|---|
| 1082DS | |
| 2162DS | FL0639-DELL-1.26.1.23978.fl |
| 4322DS | |

========================================================================

## 2. Enhancements

========================================================================

1. OpenSSL has been updated for "POODLE"

2. SSLv2 legacy option removed from serial port menu

3. Improved product security

4. Added support for MPUIQ-VMCHS when connected to PEM

========================================================================

## 3. Fixes

========================================================================

================================================================

## 4. Client/Browser

================================================================

The following chart indicates the latest version tested:

| Software | Version |
|---|---|
| Java | Version 8 Update 30 |
| Internet Explorer | 10 |
| Firefox | 36 |
| Chrome | 40 |