

DELL KVM Switch Appliances
(2161DS, 4161DS, 2321DS)
Firmware Release Notes
Version 1.4.0.6
February 23, 2016

This document outlines:

1. Appliance Support Information
2. Enhancements
3. Fixes

=====

Appliance Support Information

=====

The following appliances are supported with this release:

2161DS, 4161DS – FL0477-DELL-1.4.0.6.fl

2321DS - FL0616-DELL-1.4.0.6.fl

=====

Enhancements

=====

1. Added support for the AVRIQ-USB2 and MPUIQ-VMCHS.

=====

Fixes

=====

1. Fixed Java viewer security warnings for Java 1.7 update 51